

# Oil Field Environmental Incident Summary

**Incident:** 20140929094341

**Date/Time of Notice:** 09/29/2014 09:43

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** US 1-28

**Field Name:** WHISKEY JOE

**Well File #:** 7438

**Date Incident:** 9/27/2014

**Time Incident:** 16:00

**Facility ID Number:**

**County:** BILLINGS

**Twp:** 141

**Rng:** 100

**Sec:** 28

**Qtr:**

**Location Description:**

**Submitted By:** Rafe Espinoza

**Received By:**

**Contact Person:** Mike Obrigewitch  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 3 Mile

**Distance Nearest Water Well:** 3 Mile

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	17	Barrels			17	barrels
Brine	68	Barrels	2	Barrels	68	barrels

**Other**

**Description of Other Released Contaminant:**

Investigation is underway

**Inspected:**

**Written Report Received:** 9/29/2015

**Clean Up Concluded:** 9/28/2014

**Risk Evaluation:**

Release remained on site, and response crews were there within the hour of reported incident.

**Areal Extent:**

Release was contained within treater secondary containment

***Potential Environmental Impacts:***

Investigation is underway.

***Action Taken or Planned:***

Excavation of material determine will determine cause of release. Once that is determined corrective actions will be addressed.

***Wastes Disposal Location:*** Chimney Butte.

***Agencies Involved:*** ND Industrial Commission, and US Forest Service

***Updates***

---

***Date:*** 9/29/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.